

# BE/BI Specialists List

(version 2017)

Instructions for use: Always try to contact the first named person on the list before trying the others. If none of the persons listed can be reached and the matter is really urgent, call the appropriate Section Leader (BL: C. Zamantzas; EA: G. Tranquille; ML: R. Veness; PI: L. Søby; PM: F. Roncarolo; QP: T. Lefèvre; SW: S. Jackson). Finally if the Section Leader cannot be reached either, call the Group Leader O.R. Jones or his Deputy T. Lefèvre

## ----- SPS BI Coordinator: -----

EQUIPMENT	NAMES	BI Section	CERN Telephone	CERN Mobile	Private Telephone
MOPOS	Albertone, J.	QP	78229/75591	163145	06.19.67.60.14
	Boccard, C.	QP	74790/75591	164125	164125
	Jackson, S.	SW	78100	164559	09.72.32.42.57
BPM (TT10)	Bogey, T.	QP	75591	164126	022.557.19.61
	Jensen, L.	SW	62740	164757	04.50.41.05.04
BPM (TT41) AWAKE	Bogey, T.	QP	75591	164126	022.557.19.61
	Topaloudis, A	SW	70547	167115	022.525.56.63
BPMI (TI2+TI8)	Wendt, M	QP	71806	166477	09.72.46.41.58
	Baud, G	SW	70547	167317	167317
LHC BPM (LSS5)	Wendt, M	QP	71806	166477	09.72.46.41.58
	Baud, G	SW	70547	167317	167317
DC BCT	Odier, P.	PI	73817/73810	163076	022.783.04.93
	Thoulet, S.	PI	72584/73810	165486	06.81.32.28.71
	Jensen, L.	SW	62740	164757	04.50.41.05.04
Fast BCT (Ring + transfer-line)	Belohrad, D.	PI	76318/74423	163455	022.796.56.68
	Topaloudis, A	SW	70547	167115	41.05.04022.52
SEM	Duraffourg, M	PM	71933	164839	04.50.48.29.23
	Jensen, L.	SW	62740	164757	04.50.41.05.04
Servo spill	Effinger, E.	BL	70577	164950	022.362.72.26
	Fullerton, J.	SW	75038	162945	04.50.41.02.64
BLM (Ring + transfer-line)	Effinger, E.	BL	70577	164950	022.362.72.26
	Jensen, L.	SW	62740	164757	04.50.41.05.04
Tune BBQ	Gasior, M	QP	72530	163104	04.50.20.69.23
	Boccardi, A.	QP	63546	165489	022.34.10.444
	Jackson, S.	SW	78100	164559	09.72.32.42.57
BTV	Burger, S.	PM	71933	164941	164941
	Guerrero, A.	SW	75382	164805	06.14.90.75.34
	Vuitton, C.	ML	70724/76849	162903	162903
Wire-scanners	Emery, J.	BL	70559	162193	022.344.77.242
	Guerrero, A.	SW	75382	164805	06.14.90.75.34
	Vuitton, C.	ML	70724/76849	162903	162903
BI Stepping-motors	Duraffourg, M	PM	71933	164839	04.50.48.29.23
	Bart-Pedersen, S.	SW	75369	163096	09.51.01.23.54
	Vuitton, C.	ML	70724/76849	162903	162903
IPM (BGI)	Storey, J	BL	70241	162546	162546
	Guerrero, A.	SW	75382	164805	06.14.90.75.34
Head-tail	Lefevre, T.	QP	63589	165041	06.03.17.12.38
	Bart-Pedersen, S	SW	75369	163096	09.51.01.23.54
Sync. Light Monitor	Bravin, E	PM	71885	162914	162914
	Roncarolo, F	PM	76951	160747	160747

# BE/BI Specialists List

(version 5 April 2016)

**Instructions for use:** Always try to contact the first named person on the list before trying the others. If none of the persons listed can be reached and the matter is really urgent, call the appropriate Section Leader (BL: C. Zamantzas; EA: G. Tranquille; ML: R. Veness; PI: L. Søby; PM: F. Roncarolo; QP: T. Lefèvre; SW: S. Jackson).  
Finally if the Section Leader cannot be reached either, call the Group Leader O.R. Jones or his Deputy T. Lefèvre

## ----- SPS North Area BI Coordinator: J. Spanggaard -----

EQUIPMENT	NAMES	BI Section	CERN Telephone	CERN Mobile	Private Telephone
<b>Calorimeter</b> XEMC	Carriere, P	EA	62673	162545	04.50.04.88.49
	Fullerton J.	SW	75038	162945	04.50.41.02.64
<b>CEDAR</b> XCED	Spanggaard, J.	EA	75343	163629	04.50.42.40.93
	Carriere, P.	EA	62673	162545	04.50.04.88.49
	Fullerton, J.	SW	75038	162945	04.50.41.02.64
<b>Cerenkov Counter</b> XCET	Carriere, P.	EA	62673	162545	04.50.04.88.49
	Fullerton, J.	SW	75038	162945	04.50.41.02.64
<b>Experimental Scaler</b> XSCAL	Carriere, P.	EA	62673	162545	04.50.04.88.49
	Fullerton, J.	SW	75038	162945	04.50.41.02.64
<b>FISC</b> XFFV/H, XFBV/H	Deschamps, S.	EA	75889	165274	04.50.04.39.03
	Fullerton, J.	SW	75038	162945	04.50.41.02.64
<b>Ionization Chamber</b> XION (Argonion)	Carriere, P.	EA	62673	162545	04.50.04.88.49
	Fullerton, J.	SW	75038	162945	04.50.41.02.64
<b>BTV</b>	Burger, S.	PM	71933	164941	164941
	Duraffourg, M	PM	71933	164839	04.50.48.29.23
<b>MWPC</b> XWCA/XWCM	Frassier, A.	EA	63503	163626	04.50.31.78.40
	Deschamps, S	EA	75889	165274	04.50.04.39.03
	Fullerton J.	SW	75038	162945	04.50.41.02.64
<b>Scintillator</b> XSCI	Deschamps, S.	EA	75889	165274	04.50.04.39.03
	Fullerton J.	SW	75038	162945	04.50.41.02.64
<b>Spectrometer/profile</b> XDWC	Carriere, P.	EA	62673	162545	04.50.04.88.49
	Deschamps, S.	EA	75889	165274	04.50.03.39.03
	Fullerton, J.	SW	75038	162945	04.50.41.02.64
<b>SEM</b> XTBU, XTBD, . . .	Duraffourg, M	PM	71933	164839	04.50.48.29.23
	Jensen, L.	SW	62740	164757	04.50.41.05.04
<b>Timing to physicists</b>	Carriere, P.	EA	62673	162545	04.50.04.88.49
	Fullerton, J.	SW	75038	162945	04.50.41.02.64

# BE/BI Specialists List

(version 2017)

Instructions for use: Always try to contact the first named person on the list before trying the others. If none of the persons listed can be reached and the matter is really urgent, call the appropriate Section Leader (BL: C. Zamantzas; EA: G. Tranquille; ML: R. Veness; PI: L. Søby; PM: F. Roncarolo; QP: T. Lefèvre; SW: S. Jackson).  
Finally if the Section Leader cannot be reached either, call the Group Leader O.R. Jones or his Deputy T. Lefèvre

## --- PS BI Coordinator: A. Guerrero ---

(Look here first)

EQUIPMENT	NAMES	BI Section	CERN Telephone	CERN Mobile	Private Telephone
<b>Beam Loss Monitors</b>	Effinger, E.	BL	70577	164950	022.362.72.26
	Bart Pedersen S.	SW	75369	163096	09.51.01.23.54
<b>BPM (TT2)</b>	Bogey, T.	QP	75591	164126	022.557.19.61
	Jensen, L.	SW	62740	164757	04.50.41.05.04
<b>Orbit and Trajectory</b>	Belleman, J.	PI	72921	---	04.50.56.70.67
	Bozzolan, M.	PI	78951	167497	07.83.26.74.57
	Bart Pedersen S.	SW	75369	163096	09.51.01.23.54
<b>SEM Grids</b>	Duraffourg, M.	PM	71933	164839	04.50.48.29.23
	Focker, G. J.	PM	72270/70578	163439	04.50.41.56.26
	Guerrero, A.	SW	75382	164805	06.14.90.75.34
<b>Tune Measurement</b>	Gasior, M.	QP	72530	163104	04.50.20.69.23
	Jackson S.	SW	78100	164559	09.72.32.42.57
<b>Fast BCT (1000 turns)</b>	Allica, JC.	PI	74930	161293	161293
	Bart-Pedersen, S.	SW	75369	163096	09.51.01.23.54
<b>BTV</b>	Burger, S.	PM	71933	164941	164941
	Guerrero, A.	SW	75382	164805	06.14.90.75.34
<b>LSD</b>	Duraffourg, M.	PM	71933	164839	04.50.48.29.23
	Bravin, E.	PM	71885	162914	022.755.01.26
<b>Fast Wire Scanner</b>	Emery, J.	BL	70559	162193	022.344.77.24
	Guerrero A.	SW	75382	164805	06.14.90.75.34
	Andreazza, W.	ML	73287	164128	164128
<b>DC BCT</b>	Thoulet, S.	PI	72584/73810	165485	06.81.32.28.71
	Odier, P.	PI	73817	163076	022.783.04.93
	Bart-Pedersen, S.	SW	75369	163096	09.51.01.23.54
<b>Fast beam transformers (TT2, D3, nTOF)</b>	Allica, JC.	PI	74930	161293	161293
	Lenardon, F.	PI	73818/79932	164486	04.50.20.59.64
	Topaloudis, A.	SW	70547	167115	022.525.56.63
<b>WCM (PS)</b>	Belleman, J.	PI	72921	---	04.50.56.70.67
	Bart-Pedersen, S.	SW	75369	163096	09.51.01.23.54
<b>WCM (TT2, nTOF)</b>	Belleman, J.	PI	72921	---	04.50.56.70.67
	Odier, P.	PI	73817/73810	163076	022.783.04.93
<b>Pus, all others</b>	Belleman, J.	PI	72921	---	04.50.56.70.67

## BE/BI Specialists List

(version 2017)

Instructions for use: Always try to contact the first named person on the list before trying the others. If none of the persons listed can be reached and the matter is really urgent, call the appropriate Section Leader (BL: C. Zamantzas; EA: G. Tranquille; ML: R. Veness; PI: L. Søby; PM: F. Roncarolo; QP: T. Lefèvre; SW: S. Jackson). Finally if the Section Leader cannot be reached either, call the Group Leader O.R. Jones or his Deputy T. Lefèvre

### ----- PS East Hall BI Coordinator: J. Spanggaard -----

EQUIPMENT	NAMES	BI Section	CERN Telephone	CERN Mobile	Private Telephone
BTV	Burger, S.	PM	71933	164941	164941
	Guerrero A.	SW	75382	164805	06.14.90.75.34
Scintillator XSCI	Deschamps, S.	EA	75889	165274	04.50.04.39.03
	Fullerton J.	SW	75038	162945	04.50.41.02.64
Spectrometer/profile XDWC	Carriere, P.	EA	62673	162545	04.50.04.88.49
	Fullerton, J.	SW	75038	162945	04.50.41.02.64
Telescope	Deschamps, S.	EA	75889	165274	04.50.04.39.03
	Carriere, P.	EA	62673	162545	04.50.04.88.49
SEM	Deschamps, S.	EA	75889	165274	04.50.04.39.03
	Fullerton, J.	SW	75038	162945	04.50.41.02.64

### ----- LINAC2/LINAC4 BI Coordinator : F. Roncarolo -----

EQUIPMENT	NAMES	BI Section	CERN Telephone	CERN Mobile	Private Telephone
BCTs	Allica, JC.	PI	74930	161293	161293
	Lenardon, F.	PI	73818/79932	164486	04.50.20.59.64
	Topaloudis, A.	SW	70547	167115	022.525.56.63
BPMs (LINAC)	Bozzolan, M	PI	78951	167497	07.83.26.74.57
	Guillot-Vignot F.	PI	74588/73819	165884	06.17.27.70.49
	Guerrero, A	SW	75382	164805	06.14.90.75.34
SEM grids, Faraday cups, Emittance meters	Duraffourg, M	PM	71933	164839	04.50.48.29.23
	Focker, G. J.	PM	72270/70578	163439	04.50.41.56.26
	Guerrero, A.	SW	75382	164805	06.14.90.75.34
BSM	Tan, J	EA	63580	163812	04.50.43.67.07
	Rossi, A	EA	75978	163263	163263
	Bart-Pedersen, S	SW	73569	163096	09.51.01.23.54

### ----- LINAC3 BI Coordinator : F. Roncarolo -----

EQUIPMENT	NAMES	BI Section	CERN Telephone	CERN Mobile	Private Telephone
BCTs	Allica, JC.	PI	74930	161293	161293
	Lenardon, F.	PI	73818/79932	164486	04.50.20.59.64
	Topaloudis, A.	SW	70547	167115	022.525.56.63
Phase probes (LINAC3)	Søby, L.	PI	78452	163103	04.50.42.09.48
SEM grids, Faraday cups, Emittance meters	Duraffourg, M	PM	71933	164839	04.50.48.29.23
	Focker, G. J.	PM	72270/70528	163439	04.50.41.56.26
	Guerrero, A.	SW	75382	164805	06.14.90.75.34
BPMs	Bozzolan, M	PI	78951	167497	07.83.26.74.57
	Guillot-Vignot, F.	PI	75488/73819	165884	06.17.27.70.49
	Baud, G	SW	70547	167317	167317

## BE/BI Specialists List

(version 2017)

**Instructions for use:** Always try to contact the first named person on the list before trying the others. If none of the persons listed can be reached and the matter is really urgent, call the appropriate Section Leader (BL: C. Zamantzas; EA: G. Tranquille; ML: R. Veness; PI: L. Søby; PM: F. Roncarolo; QP: T. Lefèvre; SW: S. Jackson). Finally if the Section Leader cannot be reached either, call the Group Leader O.R. Jones or his Deputy T. Lefèvre

### ----- PSB BI Coordinator: M. Bozzolan -----

EQUIPMENT	NAMES	BI Section	CERN Telephone	CERN Mobile	Private Telephone
<b>Beam Loss Monitors</b>	Effinger, E.	BL	70577	164950	022.362.72.26
	Zamantzas, C.	BL	73409	162170	022.731.22.28
	Jackson, S.	SW	78100	164559	09.72.32.42.57
	Jensen, L.	SW	62740	164757	04.50.41.05.04
<b>DC BCT</b>	Thoulet, S.	PI	72584/73810	165485	06.81.32.28.71
	Odier, P.	PI	73817/73810	163076	022.783.04.93
	Jensen, L.	SW	62740	164757	04.50.
<b>Fast BCT (PSB ring)</b>	Odier, P.	PI	73817/73810	163076	022.783.04.93
	Thoulet, S.	PI	72584/73810	165485	06.81.32.28.71
<b>Fast BCT (Injection + extraction lines)</b>	Allica, J.C.	PI	74930	161293	161293
	Topaloudis, A.	SW	70547	167115	022.525.56.63
	Lenardon, F.	PI	73818/79932	164486	04.50.20.59.64
<b>WCM for BSM</b>	Odier, P.	PI	73817/73810	163076	022.783.04.93
	Thoulet, S.	PI	72584/73810	165485	06.81.32.28.71
<b>PU, closed orbit</b>	Guillot-Vignot, F.	PI	74588/73819	165884	06.17.27.70.49
	Søby, L.	PI	78452	163103	04.50.42.09.48
	Bart-Pedersen, S.	SW	73569	163096	09.51.01.23.54
<b>PU, PSB to PS transfer</b>	Bozzolan, M.	PI	78951	167497	07.83.26.74.57
	Guillot-Vignot, F.	PI	74588/73819	165884	06.17.27.70.49
	Topaloudis, A.	SW	70547	167115	022.525.56.63
<b>SEM grids</b>	Duraffourg, M.	PM	71933	164839	04.50.48.29.23
	Guerrero, A.	SW	75382	164805	06.14.90.75.34
<b>BTV</b>	Burger, S.	PM	71933	164941	164941
	Guerrero, A.	SW	75382	164805	06.14.90.75.34
<b>Fast Wire Scanners</b>	Emery, J.	BL	70559	162193	022.344.77.24
	Guerrero A.	SW	75382	164805	06.14.90.75.34
	Andreazza, W.	ML	73287	164128	164128
<b>Half-turn PU position measurement</b>	Tan, J.	PI	63580	163812	04.50.43.67.07
	Søby, L.	PI	78452	163103	04.50.42.09.48
<b>Tune measurement</b>	Gasior, M.	QP	72530	163104	04.50.20.69.23
	Jackson S.	SW	78100	164559	09.72.32.42.57

### ----- ISOLDE BI Coordinator: G.J. Focker -----

<b>ISOLDE Scanners</b>	Focker, GJ. Bart-Pedersen, S.	PM SW	72270/70578 75369	163439 163096	04.50.41.56.26 09.51.01.23.54
<b>ISOLDE Grids</b>	Focker, GJ. Bart-Pedersen, S.	PM SW	72270/70578 75369	163439 163096	04.50.41.56.26 09.51.01.23.54
<b>ISLODE Faraday cups</b>	Focker GJ. Bart Pedersen S.	PM SW	72270/70578 75369	163439 163096	04.50.41.56.26 09.51.01.23.54
<b>ISOLDE tape station</b>	Focker GJ. Bart-Pedersen, S.	PM SW	72270/70578 75369	163439 163096	04.50.41.56.26 09.51.01.23.54
<b>ISOLDE FNBS</b>	Focker, GJ. Bart-Pedersen, S.	PM SW	72270/70578 75369	163439 163096	04.50.41.56.26 09.51.01.23.54
<b>REX ISOLDE BD Boxes</b>	Duraffourg, M. Bart-Pedersen, S.	PM SW	71933 75369	164839 163096	04.50.48.29.23 09.51.01.23.54

# BE/BI Specialists List

(version 2017)

**Instructions for use:** Always try to contact the first named person on the list before trying the others. If none of the persons listed can be reached and the matter is really urgent, call the appropriate Section Leader (BL: C. Zamantzas; EA: G. Tranquille; ML: R. Veness; PI: L. Søby; PM: F. Roncarolo; QP: T. Lefèvre; SW: S. Jackson). Finally if the Section Leader cannot be reached either, call the Group Leader O.R. Jones or his Deputy T. Lefèvre

----- LEIR BI Coordinator: E.B. Holzer -----					
EQUIPMENT	NAMES	BI Section	CERN Telephone	CERN Mobile	Private Telephone
DC BCT	Thoulet, S.	PI	72584/73810	165485	06.81.32.28.71
	Odier, P.	PI	73817/73810	163076	022.783.04.93
	Bart Pedersen, S.	SW	75369	163096	09.51.01.23.54
Fast beam transformers	Allica, J.C.	PI	74930	161293	161293
	Lenardon, F.	PI	73818/79932	164486	04.50.20.59.64
	Topaloudis, A.	SW	70547	167115	022.525.56.63
Schottky & Wide Band PUs	Marqversen, O.	PI	74605	161462	161462
PUs, closed orbit	Marqversen, O.	PI	74605	161462	161462
	Guillot-Vignot, F.	PI	74588/73819	165884	06.17.27.70.49
	Fullerton, J.	SW	75038	162945	04.50.41.02.64
PUs, LEIR to PS Transfer	Guillot Vignot, F.	PI	74588/73819	165884	06.17.27.70.49
	Søby, L.	PI	78452	163103	04.50.42.09.48
	Baud, G	SW	70547	167317	167317
Tune measurement	Gasior, M	QP	72530	163104	04.50.20.69.23
	Jackson, S.	SW	78100	164559	09.72.32.42.57
BTV	Burger, S.	PM	71933	164941	164941
	Guerrero, A.	SW	75382	164805	06.14.90.75.34
SEM Grids	Duraffourg, M.	PM	71933	164839	04.50.48.29.23
	Focker, G.J.	PM	72270/70578	163439	04.50.41.56.26
	Guerrero, A.	SW	75382	164805	06.14.90.75.34
BIPM	Tranquille, G.	EA	70243/72554	160899	04.50.20.86.64
	Frassier, A.	EA	63503	163626	04.50.31.78.40
LEIR Electron Cooling	Tranquille, G.	EA	70243/72554	160899	04.50.20.86.64
	Frassier, A.	EA	63503	163626	04.50.31.78.40
	J. Cenede	EA	76069	161433	06.13.74.35.62

## BE/BI Specialists List

(version 2017)

Instructions for use: Always try to contact the first named person on the list before trying the others. If none of the persons listed can be reached and the matter is really urgent, call the appropriate Section Leader (BL: C. Zamantzas; EA: G. Tranquille; ML: R. Veness; PI: L. Søby; PM: F. Roncarolo; QP: T. Lefèvre; SW: S. Jackson).  
Finally if the Section Leader cannot be reached either, call the Group Leader O.R. Jones or his Deputy T. Lefèvre

### ----- AD/ELENA BI Coordinator: G. Tranquille -----

EQUIPMENT	NAMES	BI Section	CERN Telephone	CERN Mobile	Private Telephone
Fast BCTs	Allica, J.C.	PI	74930	161293	161293
	Lenardon, F.	PI	73818/79932	164486	04.50.20.59.64
	Topaloudis, A.	SW	70547	167115	022.525.56.63
PUs (closed orbit & e-cooling)	Marqvorsen, O	PI	74605	161462	161462
	Guillot-Vignot, F.	PI	74588/73819	165884	06.17.27.70.49
	Louro, D	SW	63018	167158	04.50.41.55.91
BIPM	Tranquille, G.	EA	63490	160899	04.50.20.86.64
	Frassier, A.	EA	63503	163626	04.50.31.78.40
BTV	Burger, S.	PM	71933	164941	164941
	Guerrero, A.	SW	75382	164805	06.14.90.75.34
GEM	Deschamps, S	EA	75889	165274	04.50.04.39.03
	Carriere, P.	EA	62673	162545	04.50.04.88.49
	Fullerton, J.	SW	75038	162945	04.50.41.02.64
AD Electron Cooling	Tranquille, G.	EA	63490	160899	04.50.35.40.86
	Frassier, A.	EA	63503	163626	04.50.31.78.40
	J. Cenede	EA	76069	161433	06.13.74.35.62
Transverse Schottky/BTF	Belohrad, D.	PI	76318/74423	163455	022.796.56.68
	Angoletta, ME.	BE/RF	72479	164283	164283
Tune	Gasior, M.	QP	72530	163104	04.50.20.69.23
	Jackson, S.	SW	78100	164559	09.72.32.42.57

### ----- CTF3 BI Coordinator: T. Lefèvre -----

EQUIPMENT	NAMES	BI Section	CERN Telephone	CERN Mobile	Private Telephone
WCMs	Odier, P.	PI	73817/73810	163076	022.783.04.93
BPMs	Guillot Vignot, F.	PI	74588/73819	165884	06.17.27.70.49
	Søby, L.	PI	78452	163103	04.50.42.09.48
	Topaloudis, A.	SW	70547	167115	022.525.56.63
BTV	Burger, S.	PM	71933	164941	164941
	Guerrero, A.	SW	75382	164805	06.14.90.75.34